

POLLENSZŰRŐ PC8588

LAND ROVER

| | | |
|--|----------|---------------------|
| Defender (L663) 2.0 P300 221KW(300PS/HP) - 1997cc - Motor PT204 | (09/19-) | |
| Defender (L663) 2.0 P400e Hybrid 297KW(404PS/HP) - 1997cc - Motor PT204 | (09/20-) | |
| Defender (L663) 3.0 D200 MHEV 147KW(200PS/HP) - 2997cc - Motor AJ20D6 | (09/20-) | |
| Defender (L663) 3.0 D250 MHEV 183KW(249PS/HP) - 2997cc - Motor AJ20D6 | (09/20-) | |
| Defender (L663) 3.0 D300 MHEV 221KW(300PS/HP) - 2997cc - Motor AJ20D6 | (09/20-) | |
| Defender (L663) 3.0 P300 MHEV 221KW(300PS/HP) - 2996cc - Motor AJ20P6 | (05/22-) | |
| Defender (L663) 3.0 P400 MHEV 294KW(400PS/HP) - 2996cc - Motor PT306 | (09/19-) | |
| Defender (L663) 5.0 P525 386KW(525PS/HP) - 5000cc - Motor 508PS | (05/21-) | |
| Defender (L663) D200 SD4 147KW(200PS/HP) - 1999cc - Motor 204DT | (09/19-) | |
| Defender (L663) D240 SD4 177KW(241PS/HP) - 1999cc - Motor 204DT | (09/19-) | |
| Discovery V 2.0 221KW(300PS/HP) - 1997cc - Motor PT204 | (09/17-) | Chassis L2426463--> |
| Discovery V 2.0 D 132KW(180PS/HP) - 1999cc - Motor 204DTD | (09/15-) | Chassis L2426463--> |
| Discovery V 2.0 D 177KW(241PS/HP) - 1999cc - Motor 204DTA | (09/16-) | Chassis L2426463--> |
| Discovery V 3.0 250KW(340PS/HP) - 2995cc - Motor 306PS | (09/16-) | Chassis L2426463--> |
| Discovery V 3.0 D 225KW(306PS/HP) - 2993cc - Motor 306DT | (09/18-) | Chassis L2426463--> |
| Discovery V 3.0 D 155KW(211PS/HP) - 2993cc - Motor 306DT | (09/16-) | Chassis L2426463--> |
| Discovery V 3.0 D 183KW(249PS/HP) - 2993cc - Motor 306DT | (09/16-) | Chassis L2426463--> |
| Discovery V 3.0 D 190KW(258PS/HP) - 2993cc - Motor 306DT | (09/16-) | Chassis L2426463--> |
| Discovery V 3.0 D250 MHEV 183KW(249PS/HP) - 2997cc - Motor AJ20D6 | (12/20-) | Chassis L2426463--> |
| Discovery V 3.0 D300 MHEV 221KW(300PS/HP) - 2997cc - Motor AJ20D6 | (12/20-) | Chassis L2426463--> |
| Discovery V 3.0 P360 MHEV 265KW(360PS/HP) - 2996cc - Motor AJ20P6 | (12/20-) | Chassis L2426463--> |