

POLLENSZÜRŐ E849

FORD

Ranger (TKE) 2.0 EcoBlue 130 96KW(130PS/HP) - 1995cc - Motor T20DD0J	(03/19-)
Ranger (TKE) 2.0 EcoBlue 170 125KW(170PS/HP) - 1995cc - Motor T20DD0J	(03/19-)
Ranger (TKE) 2.0 EcoBlue 180 132KW(179PS/HP) - 1995cc - Motor T20DD0J	(09/18-)
Ranger (TKE) 2.0 EcoBlue 213 157KW(213PS/HP) - 1995cc - Motor T20DD0J	(03/19-)
Ranger (TKE) 2.2 TDCi 120 88KW(118PS/HP) - 2198cc - Motor GBVAJPF	(04/11-)
Ranger (TKE) 2.2 TDCi 125 92KW(125PS/HP) - 2198cc - Motor GBVAJQW	(04/11-)
Ranger (TKE) 2.2 TDCi 130 96KW(131PS/HP) - 2198cc - Motor T22DD0P	(05/15-)
Ranger (TKE) 2.2 TDCi 160 118KW(160PS/HP) - 2198cc - Motor T22DD0P	(05/15-)
Ranger (TKE) 2.5 i 122KW(166PS/HP) - 2488cc - Motor GBVAF, GBVAK, GBVAL	(07/19-)
Ranger (TKE) 2.5i 4x4 122KW(164PS/HP) - 2488cc - Motor GBVAL	(11/11-)
Ranger (TKE) 3.2 TDCi 200 147KW(197PS/HP) - 3198cc - Motor SAFA	(04/11-)
Ranger (TKE) 2.2 TDCi 150 110KW(148PS/HP) - 2198cc - Motor GBVAJQJ	(04/11-)

MAZDA

BT50 II 2.2 MZ-CD 92KW(125PS/HP) - 2198cc - Motor P4AT	(12/12-)
BT50 II 2.2 MZ-CD 88KW(120PS/HP) - 2198cc - Motor P4AT	(11/11-)
BT50 II 2.2 MZ-CD 110KW(150PS/HP) - 2198cc - Motor P4AT	(11/11-)
BT50 II 2.5 MZI 122KW(166PS/HP) - 2488cc - Motor L5Y3	(11/11-)
BT50 II 3.2 MZ-CD 147KW(200PS/HP) - 3198cc - Motor P5AT	(11/11-)